

OU(s): 01	Issue Category: Monitoring			
	Issue: Additional monitoring wells are needed downgradient of MW-5 due to increasing concentrations in that well.			
	Recommendation: Investigate the appropriate location and install the downgradient wells for inclusion in the annual monitoring.			
Affect Current Protectiveness	Affect Future Protectiveness	Party Responsible	Oversight Party	Milestone Date
No	Yes	EPA	EPA	7/26/2017